SCANGRIP®

SUNMATCH 4

03.5657

CCT SCAN - Stepless

USE
Activate the CCT SCAN function to sweep stepless in the interval from 2500K to 6500K. At any point, the CCT SCAN function can be locked.

To save battery and avoid the risk of overheating an intelligent built-in system switches turn the lamp to low mode after 3 minutes of use at high mode.

Stepless dimmer 10-100%

3

years warranty*

* go to scangrip.com to register

Ultra high CRI+ COB LED Spot: High power LED	50-500 lm Spot: 200 lm	700-1400 lux@0.5m Spot: 5000 lux@0.5m	2500K-6500K Spot: 4000K	CRI 96+ Spot: 95 CRI
3.7V / 2600mAh Li-ion	2-10h Spot: 3h	4h	-10° to +40° C	1m
IK07	IP65	188x58x26mm	267g	Included USB cable Charging input 5V DC 1A

UK   SUNMATCH 4

WARNING

- Always respect applicable legislation for working with electrical equipment to reduce the risk of accidents.
- Avoid looking directly into the beam of light, as this will result in dazzling.
- Do not use the lamp near a naked flame.
- The light source of this luminaire is not replaceable; when the light source reaches its end of life the whole luminaire shall be replaced.

USE

- Press the on/off button to turn the lamp on in the sequence: Main > Spot > Off.
- Press and hold the on/off button while the main light is on to start dimming. Release, press, and hold again to increase.
- At the lowest and highest levels, the light will flash until the button is released.
- When the lamp is turned off the lamp will remember the setting of the main light.
- When the light is on, press the CCT SCAN button to change the color temperature manually.
- When the light is on, press and hold the CCT SCAN button for 2 seconds to activate the CCT SCAN mode.
- When in CCT SCAN mode, press the CCT SCAN button to pause the CCT SCAN mode.
- When in CCT SCAN mode, press and hold the CCT SCAN button for 2 seconds to deactivate CCT SCAN mode. When in CCT Scan mode, the CCT indicator corresponds to the following color temperature ranges: 25: 2500-3300K, 35: 3301-4100K, 45: 4101-4900K, 55: 4901-5700K, 65: 5701-6500K.
- To save battery and avoid the risk of overheating an intelligent built-in system turn the lamp to low mode (250 lumen) after 3 minutes of use at high mode (500 lumen).

CHARGING / BATTERY

- During charging, the 4 led bars will indicate the level of charge in red color. When fully charged, all 4 led bars will light up with green color.
- Battery capacity indicator: when the lamp is OFF, press and hold on/off button for 2 sec. (Capacity indicator function is disabled when the lamp is on).
- Use 5V, 1A USB charger.
- Always replace the battery with a new one of the same type and grade.
- Don't leave battery discharged. Otherwise, it could be over-discharged and may NOT be able to be recharged.