



Important. Please read instructions before use.

The Robert Sorby Hollowmaster has a flat underside which provides exceptional control and stability when hollowing and is suitable for end grain and bowl work. It is supplied with two interchangeable tips for hollowing and scraping.


EQUIPMENT



LATHE SET-UP




With the tool rest set on centre, place the flat underside of the Hollowmaster on the rest.




Always use the tool with the straight part of the shaft on the tool rest.


TOOL USE




An initial centre hole can be pre-drilled.



To form the initial shape, use sweeping cuts from the centre outwards.




Stop and check the wall thickness at regular intervals.




A smooth finish is achieved using the scraper tip.

SAFETY



Always switch the lathe off to clear shavings.

SHARPENING



Both tips can be sharpened using a flat sharpening stone or a diamond file (ref RS224). For the perfect sharp edge use the cutter holder (ref 472) in conjunction with the Robert Sorby ProEdge (472 is not suitable for Midi Hollowmaster ref RS130KT).